



ENGINE REPORT

GEN 3

LOT # 8

MAKE: ISUZU MODEL: A-4JG1 S/N: 4JG1NAACA-01

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: STAMFORD 35KVA GEN

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>STARTS good. EVERYTHING</u> <u>LOOKS good on the</u> <u>UNIT!</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(4297 HRS)</u>
After Cooler	<input type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() PSI</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(75 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

GEN #2

LOT # 9

MAKE: ISUZU MODEL: 2 Cylinder S/N: NO TAG

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: GENERATOR 21.8 KVA

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start			
Engine Smoke			
Turbocharger			
Hour Meter			(2161) HRS)
After Cooler			
Fuel Priming Pump			() PSI)
Oil Pump			() PSI)
Cooling System			() TEMP)

Additional Comments: NO FAN BELTS ON ENGINE.

SO WE COULDN'T START UP

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

GEN 5

LOT # 10

MAKE: ISUZU MODEL: 4LE1 S/N: P.N.O. 8973277510

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: GEN (NOTING)

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start			
Engine Smoke			
Turbocharger			
Hour Meter			<u>(25377 HRS)</u>
After Cooler			
Fuel Priming Pump			<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>		<u>(73 PSI)</u>
Cooling System			<u>() TEMP)</u>

Additional Comments: STARTED ENGINE, HAS OIL LEAK COMING

UNDER MOTOR SOMEWHERE

SQUEALING SOUND COMING OUT OF UNIT

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LOT # 11

MAKE: IZUZU MODEL: 4BG1 S/N: NOTA9

INSPECTED BY: Bob Cocks DATE: July 7/2010

THIS ENGINE POWERS A: STAMFORD 68.75 KVA

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start			
Engine Smoke			
Turbocharger			
Hour Meter			<u>14693</u> HRS)
After Cooler			
Fuel Priming Pump			() PSI)
Oil Pump			() PSI)
Cooling System			() TEMP)

Additional Comments: COULDN'T START ENGINE DO TO NO
FUEL TANK OR FUEL LINES

MOTOR ISN'T SIEZED TURNS OVER FINE

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LOT # 12

MAKE: Cummins MODEL: 6cyl S/N: NO TAG

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: MACNAPLUS 219KVA

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start			<u>STARTED MOTOR</u>
Engine Smoke			<u>NOTE MOTOR SOUNDS good</u>
Turbocharger	<input checked="" type="checkbox"/>		<u>NO FUEL TANK</u>
Hour Meter			<u>(3404 HRS)</u>
After Cooler			
Fuel Priming Pump			<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>		<u>(70 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>		<u>() TEMP)</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

GEN II

LOT # 13

MAKE: ISUZU MODEL: BV-4LE1 S/N: 4LE1-689359

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: GENERATOR / LIGHT TOWER 25KVA

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>STARTS + RUNS AS NEW</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>1477 HRS)</u>
After Cooler	<input type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(55 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

GEN 10

LOT # 14

MAKE: PERZEL MODEL: BV-4LE1 S/N: BLE1-684660

INSPECTED BY: Bob Cocks DATE: July

THIS ENGINE POWERS A: GENERATOR / LIGHT TOWER 25KVA

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>AS NEW</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Turbocharger	<input type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(1775)</u> HRS)	
After Cooler	<input type="checkbox"/>	<input type="checkbox"/>		
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>()</u> PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(35)</u> PSI)	
Cooling System	<input type="checkbox"/>	<input type="checkbox"/>	<u>()</u> TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LT 330

LOT # 15

MAKE: POWERSTROKE MODEL: 6.7L S/N: 1FT8W3BT2BEC59587

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2011 FORD F350 KING RANCH
CREW CAB 4X4 PICKUP
238256 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>NO OIL PRESSURE GAUGE</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(6856 HRS)</u>
After Cooler	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI)</u>
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>
Cooling System	<input type="checkbox"/>	<input type="checkbox"/>	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LT70

LOT # 16

MAKE: DURAMAX MODEL: 6.6L S/N: 1G2T423C88BF15331

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2011 GMC SIERRA 3500 HD
CREW CAB 4X4 Dually Flatbed Pickup
238256 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>Noob BATTERIES</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input type="checkbox"/>	<input type="checkbox"/>	
After Cooler	<input type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	
Oil Pump	<input type="checkbox"/>	<input type="checkbox"/>	
Cooling System	<input type="checkbox"/>	<input type="checkbox"/>	
		() HRS)	
		() PSI)	
		<u>580Kpa</u> PSI)	
		() TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LT325

LOT # 17

MAKE: POWER STROKE MODEL: 6.4 L S/N: 1FTWW31R99EA05298

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2009 FORD F350 FX4
CREW CAB 4X4 Pickup
268178 km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>NO OIL Pressure Gauge</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input type="checkbox"/>	<input type="checkbox"/>	<u>(9274 HRS)</u>
After Cooler	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI</u>
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI</u>
Oil Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP</u>
Cooling System	<input type="checkbox"/>	<input type="checkbox"/>	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LT44

LOT # 18

MAKE: DURAMAX MODEL: 6.6L S/N: 16CHK29D07E112809

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2007 CHEVROLET SILVERADO 2500HD
EXTENDED CAB 4X4 PICKUP
219731 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(3489.5 HRS)
After Cooler	<input type="checkbox"/>	<input type="checkbox"/>	(PSI)
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	(310 KPA PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(TEMP)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

BT 79

LOT # 31

MAKE: CAT MODEL: 3406 S/N: 32J01228

INSPECTED BY: Bob Cocks DATE: July 7/

THIS ENGINE POWERS A: 1991 KENWORTH C500B
T/A Rig-up Bed Truck
121527

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>4212</u> HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(<u> </u> PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(<u>62</u> PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(<u> </u> TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

T 312

LOT # 32

MAKE: CUMMINS MODEL: ISX 14.9L S/N: 26037283

INSPECTED BY: Bob Cooks DATE: July 7/2020

THIS ENGINE POWERS A: 2005 INTERNATIONAL 9900i
T/A TRUCK TRACTOR
94192 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(4382 HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	(PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(42 PSI)
Cooling System	<input type="checkbox"/>	<input type="checkbox"/>	(TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

T 308

LOT # 33

MAKE: CUMMINS MODEL: ISX 14.9L S/N: 23027759

INSPECTED BY: Bob Parks DATE: July 7/2020

THIS ENGINE POWERS A: 2005 INTERNATIONAL 9900i
T/A TRUCK TRACTOR
245042 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(8318 HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	(PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(40 PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

T309

LOT # 34

MAKE: CUMMINS MODEL: ISX 14.9L S/N: 26001818

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2005 INTERNATIONAL 9900i
T/A DAY Cab TRACK TRACTOR
100024 km

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

(5283 HRS)

(PSI)

(40 PSI)

(TEMP)

COMMENTS

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

AC901

LOT # 35

MAKE: YANMAR MODEL: 4TNV98T S/N: M1004
-2NIRD

INSPECTED BY: Bob Cocks DATE: JULY 8/2020

THIS ENGINE POWERS A: DOOSAN PORTABLE ROTARY SCREW AIR
COMPRESSOR

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>MOTOR STARTED AND</u>
Engine Smoke	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>RAN good</u>
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(<u>566</u> HRS)	
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>NO OIL PRESSURE Gauge</u>
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LOT # 36

MAKE: KATO MODEL: U3300-DI-T-ES S/N: 3KBYL03.34AD

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: Bob CAT S220 Turbo

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>DOESN'T HAVE OIL PRESSURE</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>PSI GAUGE</u>
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(6071 HRS)</u>
After Cooler	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>IT SHOWS OIL PRESSURE</u>
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>AT 2/3 2/3</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() PSI</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(good) PSI</u>
			<u>() TEMP</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LOT # 37

MAKE: PERKINS MODEL: AA S/N: U641254Y

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: SELICK SD-80 FORKLIFT

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(9362 HRS)
After Cooler	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	(PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(45 PSI)
Cooling System	<input type="checkbox"/>	<input type="checkbox"/>	(TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

LOT # 38

MAKE: CAT MODEL: 3116 S/N: 4TF70370

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: CAT IT28G Loader

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>NO OIL PRESSURE gauge</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>RUNS AND WORKS good</u>
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>(17780 HRS)</u>
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() PSI</u>
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() PSI</u>
Oil Pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>() TEMP</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

CT 321

LOT # 40

MAKE: CAT MODEL: C-13 125L S/N: 5CPXH0763EBK

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2006 STERLING L9500 TRI-AXLE
CEMENT MIXER TRUCK
617468 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(8403</u> HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(40</u> PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

WT 306

LOT # 41

MAKE: INTERNATIONAL MODEL: DT 570 9.3L S/N: 382064 REMAN

INSPECTED BY: Bob Cocks DATE: July 2/2020

THIS ENGINE POWERS A: 2006 INTERNATIONAL 7500
T/A WATER TRUCK
67849 km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(2982 HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(72 PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

WT 307
WATER TRUCK

LOT # 42

MAKE: INTERNATIONAL MODEL: DT 570 9.3 S/N: D 340 CFF

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2006 INTERNATIONAL 7500
T/A WATER TRUCK
59318 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>THERE WAS BLOWN FUSE</u> <u>UNDER HOOD</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>8897</u>
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(7777) HRS</u>
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>HAD TO SHUT ENGINE OFF</u>
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>WITH AIR KILL</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() PSI</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(60) PSI</u>
			<u>() TEMP</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

5468

LOT # 43

MAKE: INTERNATIONAL MODEL: 466 7.6L S/N: ~~5H115849~~ 5H115849

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2005 INTERNATIONAL DURASTAR 4400
S/A EXTENDED CAB SERVICE TRUCK
350026 km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(11926</u> HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>()</u> PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(60</u> PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>()</u> TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

P65

LOT # 44

MAKE: PACCAR MODEL: 8.3L S/N: PX8

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2008 PETERBILT 340
7/A Boom TRUCK
15468 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>7119</u> HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	() PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(<u>25</u>) PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

P62

LOT # 45

MAKE: MAK MODEL: E-7 S/N: 8F0429

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 1998 MAK RD 688S
T/A Boom TRUCK
286247 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>10587</u> HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	(<u> </u> PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(<u>75</u> PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(<u> </u> TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

PIPE/WATER TRUCK
PT 319

LOT #

46

MAKE: CAT

MODEL: C-13

S/N: LEE 07276

INSPECTED BY: Bob Cocks

DATE: July 7/2020

THIS ENGINE POWERS A: 2008 STERLING LT 9500

T/A PIPE/WATER TRUCK PT 319
19832 km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	✓		
Engine Smoke		✓	
Turbocharger	✓		
Hour Meter	✓		(2014 HRS)
After Cooler	✓		
Fuel Priming Pump		✓	(PSI)
Oil Pump	✓		(60 PSI)
Cooling System			(TEMP)

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

PIPE/WATER TRUCK
PT 317

LOT # 47

MAKE: CAT MODEL: C-13 S/N: LEE 07241

INSPECTED BY: Bob Cook DATE: July 7/2020

THIS ENGINE POWERS A: 2008 STERLING LT9500
T/A PIPE WATER TRUCK PT317
23972 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(2149 HRS)</u>
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(60 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

PT 315

LOT # 48

MAKE: CAT MODEL: C-13 S/N: LEE06334

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2008 STERLING 1T9500
T/A PIPE/WATER TRACK PT315
16614 KM

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(1909 HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() PSI
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(50 PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP

Additional Comments: NO BATTERIES IN TRACK

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

PT 316

LOT # 49

MAKE: CAT MODEL: C-13 S/N: LEE 07295

INSPECTED BY: Bob Cooks DATE: July 7/2020

THIS ENGINE POWERS A: 2008 STERLING LT9500
T/A PIPE/WATER TRUCK PT 316
16324 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input type="checkbox"/>	<input type="checkbox"/>	<u>(465.5 HRS)</u>
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(55 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

PT318

LOT # 50

MAKE: CAT MODEL: C-13 S/N: LEE 07320

INSPECTED BY: Bob Cooks DATE: July 7/2020

THIS ENGINE POWERS A: 2008 STERLING LT9500
T/A PIPE/WATER TRACK PT318
58852 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(3322 HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() PSI)
Fuel Priming Pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	() PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(60) PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

WT 16

LOT # 51

MAKE: MACK MODEL: E-7 S/N: 7N1624

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 1998 MACK RD688S
7/A WATER/PIPE TRUCK WT 16
386166km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(14826 HRS)</u>
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(80 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>

Additional Comments: NO BATTERY

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

WT 17

LOT # 52

MAKE: MAK MODEL: E-7 S/N: 8R2949

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 1998 MAK RD688S

T/A WATER / PIPE TRUCK WT 17

433142 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(13241</u> HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>(</u> PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(72</u> PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 701

LOT # 53

MAKE: CAT MODEL: C-13 125L S/N: NO TAG

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2004 CRANE CARRIER
TOP DRIVE DRILLING UNIT
621961 km

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() HRS)	
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(<u>45</u> PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 708

LOT # 54

MAKE: CAT

MODEL: C-13

S/N: NOT LEDGERABLE

INSPECTED BY: Bob Cocks

DATE: July 7/2020

THIS ENGINE POWERS A: 2007 CRANE CARRIER

TOP DRIVE DRILLING RIG

6799 Km

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input type="checkbox"/>	<input checked="" type="checkbox"/>	() HRS	
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() PSI	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(45) PSI	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP	

Additional Comments:

DECK ENGINE DETROIT V12 S/N 5352004986

HRS 6109

OIL PRESSURE 138 PSI

HAS TURBO

HAS AFTER COOLER

NOTE: MOTOR SOUNDS REAL GOOD

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 403

LOT # 55

MAKE: CUMMINS MODEL: ISX 14.9L S/N: 26013253

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2006 INTERNATIONAL 5600i WATER WELL
CORING UNIT
31446 Km

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>

(11580) HRS)

() PSI)

(40) PSI)

() TEMP)

COMMENTS

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 401

LOT # 56

MAKE: CUMMINS

MODEL: DT530 81L S/N: 673341-103

INSPECTED BY: Bob Cocks

DATE: July 7/2020

THIS ENGINE POWERS A: 3000 INTERNATIONAL K5070

WATER WELL / CORING UNIT

967037 Km

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>

(29840 HRS)

(PSI)

(60 PSI)

(TEMP)

COMMENTS

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 402

LOT # 57

MAKE: CUMMINS MODEL: ISX 14.9L S/N: 23064682

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2005 INTERNATIONAL PAYSTAR 5600i
WATER WELL / CORING UNIT

371331

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input type="checkbox"/>	<input type="checkbox"/>	(12227 HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	() PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(40 PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 501

LOT # 58

MAKE: CUMMINS MODEL: ISX 14.9L S/N: ?

INSPECTED BY: _____ DATE: JULY 7/2020

THIS ENGINE POWERS A: 2005 INTERNATIONAL 5600i

WATER WELL / CORING UNIT

351848 km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>NOTE: COULDN'T OPEN HOOD</u> <u>DO BRACKET MAST RESTS ON</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(11310 HRS)</u>
After Cooler	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI)</u>
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>(42 PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 709

LOT # 59

MAKE: Cummins MODEL: ISX 14.9L S/N: 26019004

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2006 INTERNATIONAL 5900i
WATER WELL / CORING UNIT
143942 KM

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(15172 HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	(PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(40 PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 508

LOT # 60

MAKE: CAT MODEL: 3406 S/N: 2WG-10817

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 1999 PETERBILT
WATER WELL UNIT
577598 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(7680 HRS)</u>
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(76 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 515

LOT # 61

MAKE: CAT MODEL C15 14.6L S/N: MBN05766

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2003 INTERNATIONAL 5600i
WATER WELL / CORING UNIT
30416 Km

ENGINE CHECK LIST:

Engine Easy To Start
 Engine Smoke
 Turbocharger
 Hour Meter
 After Cooler
 Fuel Priming Pump
 Oil Pump
 Cooling System

YES	NO
	<input checked="" type="checkbox"/>
	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	

(14662 HRS)

(PSI)

(75 PSI)

(TEMP)

COMMENTS

HARD START NEEDS FUEL
FILTERS MANGA

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 516

LOT # 62

MAKE: Cummins MODEL: ISX 14.9L S/N: 26011112

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2006 INTERNATIONAL 5600i
WATER WELL UNIT
22872km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>HAD TO SHORT SELENOID</u>
Engine Smoke	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(9920 HRS)</u>
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(40 PSI)</u>
Cooling System	<input type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 703

LOT # 63

MAKE: MAK MODEL: E-7 S/N: 4R0462

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2005 MAK CV713
WATER WELL UNIT

976288 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input type="checkbox"/>	<input type="checkbox"/>	<u>(14135 HRS)</u>
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(60 PSI)</u>
Cooling System	<input type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 710

LOT # 64

MAKE: DETROIT MODEL: SERIES 60 S/N: 06R0660642

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2002 STERLING L9500
WATER WELL UNIT
845698 km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(13485 HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	() PSI
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(95) PSI
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 11

LOT # 65

MAKE: CUMMINS MODEL: ISX 14.9L S/N: 27007621

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 2007 PETERBILT 357
WATER WELL UNIT
267720 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>18491</u> HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input type="checkbox"/>	(PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>40</u> PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 8

LOT # 66

MAKE: CAT MODEL: 3406 S/N: 3ZJ37676-1

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: 1993 MACK CL653

WATER WELL UNIT

327951 Km

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(12789</u> HRS)
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> PSI)
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(68</u> PSI)
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

Rig 707

LOT # #67

MAKE: DETROIT MODEL: 671 DIESEL S/N: 6A265037

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: COLUMBIA 3-AXLE BACK IN TRAILER
COOPER LTO-350 D/D WELL SERVICE RIG

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Turbocharger	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Hour Meter	<input type="checkbox"/>	<input checked="" type="checkbox"/>	() HRS)	
After Cooler	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Fuel Priming Pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	() PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(40 PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP)	

Additional Comments: NOTE: Had to prime engine
When started up ran good

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

MST 216

LOT # 85

MAKE: INTERNATIONAL MODEL: DTA-40 S/N: 182997/C1

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: NATIONAL 83-20R TRIPLEX Pump

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

787
~~(2277)~~ HRS)

() PSI)
(X) PSI)
() TEMP)

COMMENTS

NOTE: OIL PRESSURE
GAGE NOT WORKING
IT WAS PINNED AT 100

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

MST 217

LOT # 86

MAKE: Cummins MODEL: 300 S/N: 30007880

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: OIL WELL 348 TRIPLEX PUMP

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>

9341
(~~8243~~) HRS)

() PSI)
(80 PSI)
() TEMP)

COMMENTS

24 VOLT STARTED 4 good

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

MST 218

LOT # 87

MAKE: INTERNATIONAL MODEL: 801L S/N: WS5180N1471404

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: NATIONAL TRIPLEX Pump

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>

(6103 HRS)

(PSI)

(60 PSI)

(TEMP)

COMMENTS

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

MST 219

LOT # 88

MAKE: DETROIT MODEL: SERIES 50 S/N: 04RE202713

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: GARDNER DENVER TEE TRIPLEX Pump

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>MOTOR SOUNDS good</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>9193</u>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(8675)</u> HRS)	
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(75</u> PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

MPT 220

LOT # 89

MAKE: CAT MODEL: 3306 S/N: NOT READ ABLE

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: TULSA TT560 TRIPLEX Pump

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Engine Smoke	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(7930 HRS)	
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(70 PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

PH 682

LOT # 91

MAKE: CAT MODEL: 3412 S/N: 8882401

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: HHP-1000 TRIPLEX Pump

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
✓	
✓	

() HRS)

() PSI)

() PSI)

() TEMP)

COMMENTS

AIR START
COULDN'T START ENGINE

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

PH 683

LOT # 92

MAKE: CAT MODEL: 3412 S/N: 6DT05106

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: HHP-1000 TRIPLEX Pump

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>MOTOR STARTED AND</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<u>SOUNDS GOOD</u>
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>11999</u> HRS)	
After Cooler	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(75</u> PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

PH 681

LOT # 93

MAKE: DETROIT MODEL: SERIES 60 S/N: 06R0014171

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: CONTINENTAL EMSCO DB550 Duplex Pump

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

(☒ HRS)
(☐ PSI)
(60 PSI)
(☐ TEMP)

COMMENTS

HR METER shows 280 hrs
SO EITHER CHANGED OR
DON'T WORK
ENGINE SOUNDS good

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

MP 707

LOT #

94

6A42150

MAKE: DETROIT

MODEL: TWIN 6-71

S/N: 6A418665

INSPECTED BY: Bob Cooks

DATE: _____

THIS ENGINE POWERS A: CONTINENTAL EMSCO D375 Duplex Pump

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
✓	
	✓
	✓
	✓
✓	

() HRS)
() PSI)
() PSI)
() TEMP)

COMMENTS

COULDN'T START do to
NEEDING ELECTRIC AUTO
START

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

CBT 236

LOT # 123

MAKE: ISUZU MODEL A-LBG1 S/N: _____

INSPECTED BY: _____ DATE: _____

THIS ENGINE POWERS A: MAGNAPLUS 362 PSL 1606 GENERATOR 131KVA

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start			
Engine Smoke			
Turbocharger			
Hour Meter			
After Cooler			
Fuel Priming Pump			
Oil Pump			
Cooling System			

8284 HRS)

(_____ PSI)

(_____ PSI)

(_____ TEMP)

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

CBT 238

LOT # 125

MAKE: ISUZU

MODEL: B1-4HKIX S/N: 4HK1XD1BA-01

INSPECTED BY: Bob Cocks

DATE: July 9/2020

THIS ENGINE POWERS A: STAN FORD NEWAGE 100KW GEN

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<u>MOTOR had to be primed</u>
Engine Smoke	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<u>Then STARTED UP OK</u>
Turbocharger	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>4113</u> HRS)	<u>MOTOR sounds good</u>
After Cooler	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>(</u> PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>110</u> PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>(</u> TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

CBT 217

LOT # 126

MAKE: JOHN DEERE MODEL: 12.5L S/N: R G 6125A006800

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: MARATHON GEN (NO TAG)

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>8373</u> HRS)	
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(42</u> PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> TEMP)	

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

CB 639

LOT # 127

MAKE: ISUZU MODEL: 6BG1T S/N: N05/N

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: STAMFORD 100KW GEN

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>STARTED MOTOR</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<u>SOUNDS REAL good</u>
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(19513</u> HRS)	
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> PSI)	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(65</u> PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>(</u> TEMP)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>		

Additional Comments: _____

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

C8640

LOT # 128

MAKE: ISUZU MODEL: 6B61T S/N: 6B61-128044

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: STAMFORD 100 KW GEN

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start		<input checked="" type="checkbox"/>	<u>HARD STARTING</u>
Engine Smoke	<input checked="" type="checkbox"/>		<u>NOT SMOKE</u>
Turbocharger	<input checked="" type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>		<u>(9864 HRS)</u>
After Cooler		<input checked="" type="checkbox"/>	<u>MOTOR DIDN'T SOUND BAD</u>
Fuel Priming Pump	<input checked="" type="checkbox"/>		
Oil Pump	<input checked="" type="checkbox"/>		<u>(65 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>		<u>(65 PSI)</u>
			<u>TEMP)</u>

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

DHWT 707

LOT # 129MAKE: CAT MODEL: 3306B S/N: 85210015INSPECTED BY: Bob Cocks DATE: July 9/2020THIS ENGINE POWERS A: MARATHON 200 KW

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start				<u>COULDN'T START</u>
Engine Smoke				
Turbocharger	✓			
Hour Meter		✓	() HRS)	
After Cooler		✓		
Fuel Priming Pump	✓		() PSI)	
Oil Pump	✓		() PSI)	
Cooling System	✓		() TEMP)	

Additional Comments: COULDN'T START ENGINE NO EXHAUST
GENERATOR IS DISCONNECTED
LOOKS LIKE SOMEONE WAS WORKING ON IT, THEN
JUST LEFT IT APART

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

DHWT 707

LOT # 129

MAKE: CAT MODEL: 3306B S/N: 85210015

INSPECTED BY: Bob Cocks DATE: July 9/2020

THIS ENGINE POWERS A: MARATHON 200 kW

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start				<u>COULDN'T START</u>
Engine Smoke				
Turbocharger	✓			
Hour Meter		✓	() HRS)	
After Cooler		✓		
Fuel Priming Pump	✓		() PSI)	
Oil Pump			() PSI)	
Cooling System	✓		() TEMP)	

Additional Comments: COULDN'T START ENGINE NO EXHAUST
GENERATOR IS DISCONNECTED
LOOKS LIKE SOMEONE WAS WORKING ON IT, THEN
JUST LEFT IT APART

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

BTm 106

LOT # 130

MAKE: ISUZU MODEL: A-4BG-IT 4Cly S/N: 4BG1T AABA-02

INSPECTED BY: Bob Cocks DATE: July 7/2020

THIS ENGINE POWERS A: STAMFORD 60KW GEN 75 KVA

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
Engine Smoke	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
Turbocharger	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	(7317 HRS)	
After Cooler	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	() PSI	
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	(70 PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	() TEMP)	
Cooling System	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		

Additional Comments:

GEN SEEMS to be running OK.

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

BTM 103

LOT # 136

MAKE: CAT MODEL: 3406 S/N: SCP893E2DARW

INSPECTED BY: Bob Cocks DATE: Jul, 7/2020

THIS ENGINE POWERS A: 1995 WESTERN STAR 4964F T/A Boxer Truck

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start				CANT START ENGINE
Engine Smoke				MISSING BATTERIES + CABLES
Turbocharger	✓		4301	
Hour Meter			4301	HRS)
After Cooler	✓			
Fuel Priming Pump	✓			PSI)
Oil Pump				PSI)
Cooling System				TEMP)

Additional Comments: BTM 103

ISUZU 4BGT

STAMFORD 50KW GEN 67.5KVA

MOTOR STARTED, BUT STOPPED, THERE IS NO EXHAUST
ON ENGINE IT IS LAYING ON FLOOR. COVER IS OFF GENERATOR

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

BTM 101

LOT # 137

MAKE: DETROIT

MODEL: SERIES 60 S/N: 06 R0D13275

INSPECTED BY: Bob Cocks

DATE: July 7/2020

THIS ENGINE POWERS A: 1990 GMC AERO T/A BOILER TRUCK

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start			<u>only running on 3 cylinders</u>
Engine Smoke			
Turbocharger	<input checked="" type="checkbox"/>		
Hour Meter			<u>21012</u>
After Cooler	<input checked="" type="checkbox"/>		<u>HR3)</u>
Fuel Priming Pump			<u>() PSI)</u>
Oil Pump			<u>(65 PSI)</u>
Cooling System			<u>() TEMP)</u>

Additional Comments: BTM 101 GEN

ISSUZA model LDI GA-01

STANFORD GEN 15.76 KVA

ENGINE STARTED WITH BOOST OIL PRESSURE 80 PSI

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

CDHT 201

LOT # 138

MAKE: ISUZU

MODEL: B14HKLX S/N: 4HK1-49127

INSPECTED BY: Bob Parks

DATE: July 8/2020

THIS ENGINE POWERS A: STAMFORD 50KW GEN

ENGINE CHECK LIST:

	YES	NO		COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Hour Meter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(8567 HRS)	
After Cooler	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Fuel Priming Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() PSI)	
Oil Pump	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(108 PSI)	
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	() TEMP)	

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

C.DHT 202

LOT # 139

MAKE: ISUZU

MODEL: B14HKLX

S/N: NOT REABLE

INSPECTED BY: Bob Cooks

DATE: July 8/2020

THIS ENGINE POWERS A: STAMFORD 50KW GEN

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
	<input checked="" type="checkbox"/>
	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	
<input checked="" type="checkbox"/>	

9223 HRS)

() PSI)

75 PSI)

() TEMP)

COMMENTS

MOTOR HARD STARTING
DID SMOKE

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

C-DHT 204

LOT # 140

MAKE: JOHN DEERE MODEL: 6-cyl S/N: PE4045L235025

INSPECTED BY: Bob Cocks DATE: Jul 8/2020

THIS ENGINE POWERS A: KATO LIGHT 100 KW GEN

ENGINE CHECK LIST:

	YES	NO	COMMENTS
Engine Easy To Start	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>Engine Runs good</u>
Engine Smoke	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Turbocharger	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Hour Meter	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>(3407 HRS)</u>
After Cooler	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Fuel Priming Pump	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<u>() PSI)</u>
Oil Pump	<input type="checkbox"/>	<input type="checkbox"/>	<u>(60 PSI)</u>
Cooling System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>() TEMP)</u>

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As Is, Where Is, With All Faults" and with no guarantee or warranty of any kind.



ENGINE REPORT

CDHT 243

LOT # 144

MAKE: INTERNATIONAL MODEL: 8047GK60 S/N: 04R0002530

INSPECTED BY: Bob Cocks DATE: July 8/2020

THIS ENGINE POWERS A: STANFORD 260KW GEN

ENGINE CHECK LIST:

Engine Easy To Start
Engine Smoke
Turbocharger
Hour Meter
After Cooler
Fuel Priming Pump
Oil Pump
Cooling System

YES	NO
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>

14903 HRS)

(PSI)

(75 PSI)

(TEMP)

COMMENTS

ENGINE STARTS good
AND SOUNDS good

Additional Comments:

This is merely a report, your purchase is made subject to your own inspection and risk. All engines sell "As is, Where is, With All Faults" and with no guarantee or warranty of any kind.